

# PROFILE® .04/.06 & O.S.

- Steady speed rotation (150 to 350 rpm).
- Use the instrument with a continuous, slight in and out movement.
- Passive apical instrumentation (do not force the instruments in the apical direction).
- Working time of each instrument: maximum 5/10 seconds.



